Ferotec Friction, Inc. 150 Shellyland Road Rapho Business Park PO Box 387 Mount Joy, PA 17552

(717) 492-9600 Fax: (717) 492-9601

Material Safety		D9201-0		Data Sheet	
Telephone: (717) 492-9600		Revision Date: 8/1/2013		Fax: (717) 492-9601	
I. Product Informa	tion:				
Product Name: D9201-0					
Trade Name: Flexible Brake Lining					
II. NFPA (0 = No Hazard; 4 = Severe Hazard):					
Health = 1		Reactivity = 0)	Fire = 1	
III. Ingredient Information:					
Hazardous Components	C.A.S. Num	ber Percent	OSHA PEL (mg/n	n ³) ACGIH TLV (mg/m ³)	
Barium Sulfate	7727-43-7	15-25	10	10	
Mineral Wool	Not listed	19-22	15	10	
*Zinc	7440-66-6	1-6	Not Liste	d Not Listed	
The above chemicals marked with an asterisk (*) are subject to Section 313 of Title III of the Superfund Amendments and Reauthorization Act of 1986 (SARA) Part 372 Sub Part C-Supplier Notification Requirement.					
IV. Physical Data:					
Boiling Point (°F):	NA		Evaporation Rate	(Butyl Acetate = 1): NA	
Vapor Pressure (mm Hg):	NA		Specific Gravity (Water = 1): 2.01	
Water Solubility (%):	NA		Melting Point (°F)	: NA	
Vapor Density (Air = 1):	NA		% Volatile by Vol	ume: NA	
Appearance And Odor:	Grayish-black, little or no odor				
V. Fire and Explosion Data:					
Flash Point (°F):	NA		Flammable Limits	s: LEL = NA UEL = NA	
Extinguishing Media:	Water, foam,	, dry chemical	Unusual Fire and	Explosion Hazards: None	
Special Fire Fighting Procedures: In a sustained fire, self-contained breathing apparatus (SCBA) should be worn.					
VI. Health Data: A. Summary/Risks:					
Mineral Wool Fiber: Limited evidence of carcinogenicity in humans. However, IARC concluded that Mineral Wool Fiber should be placed in Category 2B, possibly carcinogenic to humans.					
Clinical conditions which may be aggravated: Any condition generally aggravated by mechanical irritants in air or on skin.					
Target Organs:	Lungs, skin.				
Acute Health Effects:	cute Health Effects: Temporary irritation of the mouth, nose, and throat.				
Chronic Health Effects:	Possible cancer causing agent to humans (IARC).				
Primary Routes of Entry: Inhalation					

Material Safety D9201-0

Data Sheet

VI. Health Data: B. Signs/Symptoms of Overexposure:

Inhalation: May cause temporary upper respiratory irritation.

Skin Contact: Acute - Transient mechanical irritation.

Chronic - None.

Ingestion: Acute - Unlikely to occur. Observe individual, if symptoms develop, consult physician.

Chronic - None known.

Eyes: Acute - Direct contact will cause mechanical irritation.

Chronic - None known.

VI. Health Data: C. First Aid/Emergency Procedures:

Inhalation: Remove from exposure. Get medical help if irritation persists.

Skin Contact: Wash with mild soap and running water.

Ingestion: Unlikely. Consult physician if unusual reaction is noted.

Eyes: Flush with flowing water for at least 15 minutes. If symptoms persist, seek immediate medical

attention.

VII. Reactivity Data:

Conditions to Avoid: Avoid creating dust. Vacuum when possible.

Hazardous Decomposition Products: Incomplete combustion may release toxic materials.

VIII. Spill or Leak Procedures:

Procedures for Spill/Leak: Use vacuum if dust is involved.

Waste Management: In accordance with state and local regulations.

IX. Special Protection Information:

Goggles: May be appropriate in certain operations.

Gloves: May reduce skin irritation in some operations.

Respirator: NIOSH approved nuisance dust respirator if TLV is exceeded.

Ventilation: Use local exhaust ventilation.

Other: Wear long sleeved shirts, loose fitting clothing and use good personal hygiene.

Special Consideration for Repair & Maintenance of Contaminated Equipment: NA

X. Special Considerations:

Special Handling/Storage: Store in a dry place. Label information: "Any fiber or dust may be a hazard to your health. Use respirators and/or dust control measures as well as eye protection when handling or processing this product. Do not ingest."

Other: Wash with mild soap and warm water after handling. Wash work clothes separately.

The information and recommendations set forth herein are taken from sources believed to be accurate as of the date thereof; however, Ferotec Friction makes no warranty with respect to the accuracy of the information or the suitability of the recommendations and assumes no liability to any user thereof.